

**SECTION 26 12 19**  
**PAD-MOUNTED, LIQUID-FILLED, MEDIUM-VOLTAGE TRANSFORMERS**

**PART 1 - GENERAL**

**1.1 STIPULATIONS**

- A. The specifications sections "General Conditions to the Construction Contract", "Special Conditions" and "Division 01 - General Requirements" form a part of this Section by this reference thereto, and shall have the same force and effect as if printed herewith in full.

**1.2 SUMMARY**

- A. Section Includes:
  - 1. Pad-mounted, liquid-filled, medium-voltage distribution transformers, with primary and secondary bushings within or without air-terminal enclosures.

**1.3 DEFINITIONS**

- A. Bushing: An insulating structure including a central conductor, or providing a central passage for a conductor, with provision for mounting on a barrier, conducting or otherwise, for the purpose of insulating the conductor from the barrier and conducting current from one side of the barrier to the other.
- B. Bushing Elbow: An insulated device used to connect insulated conductors to separable insulated connectors on dead-front, pad-mounted transformers and to provide a fully insulated connection. This is also called an "elbow connector."
- C. Bushing Insert: That component of a separable insulated connector that is inserted into a bushing well to complete a dead-front, load break or nonload break, separable insulated connector (bushing).
- D. Bushing Well: A component of a separable insulated connector, either permanently welded or clamped to an enclosure wall or barrier, having a cavity that receives a replaceable component (bushing insert) to complete the separable insulated connector (bushing).
- E. Elbow Connector: See "bushing elbow" above.

**1.4 ACTION SUBMITTALS**

- A. Product Data:
  - 1. For each type of product.
    - a. Include rated capacities, operating characteristics, and furnished specialties and accessories.

B. Shop Drawings:

1. For pad-mounted, liquid-filled, medium-voltage transformers.
  - a. Include plans and elevations showing major components and features.
    - 1) Include plan view and cross section of equipment base, showing clearances, required workspace, and locations of penetrations for grounding and conduits.
  - b. Include details of equipment assemblies and indicate dimensions, weights, loads, required clearances, method of field assembly, components, and location and size of field connections.
  - c. Include single-line diagram.
  - d. Include list of materials.
  - e. Include nameplate data.
  - f. Manufacturer's published time-current curves of transformer line-side fuses, with transformer damage curve, inrush curve, and thru fault current indicated.

C. Field Quality-Control Submittals:

1. Field quality-control reports.

## **1.5 INFORMATIONAL SUBMITTALS**

- A. Product Certificates: For transformers, signed by product manufacturer.
- B. Source quality-control reports.

## **PART 2 - PRODUCTS**

### **2.1 SYSTEM DESCRIPTION**

- A. Electrical Components, Devices, and Accessories: Listed and labeled in accordance with NFPA 70, by qualified electrical testing laboratory recognized by authorities having jurisdiction, and marked for intended location and application.
- B. Comply with IEEE C2.
- C. Comply with IEEE C57.12.00.

### **2.2 PERFORMANCE REQUIREMENTS**

- A. Windings Material: Aluminum.
- B. Surge Arresters: Comply with IEEE C62.11, Distribution Class; metal-oxide-varistor type, fully shielded, separable-elbow type, suitable for plugging into inserts provided in line-side section of transformer. Connected in each phase of incoming circuit and ahead of disconnecting device.

- C. Winding Connections: Connection of windings and terminal markings must comply with IEEE C57.12.70.
- D. Efficiency: Comply with 10 CFR 431, Subpart K.
- E. Insulation: Transformer kVA rating must be as follows: Average winding temperature rise above 30 deg C ambient temperature must not exceed 65 deg C and 80 deg C hottest-spot temperature rise at rated kVA when tested in accordance with IEEE C57.12.90, using combination of connections and taps that give highest average winding temperature rise.
- F. Tap Changer: External handle, for de-energized operation.
- G. Enclosure Integrity: Comply with IEEE C57.12.28 for pad-mounted enclosures that contain energized electrical equipment in excess of 600 V that may be exposed to public.
- H. Mounting: Integral skid mounting frame, suitable to allow skidding or rolling of transformer in any direction, and with provision for anchoring frame to pad.
- I. Insulating Liquids:
  - 1. Mineral Oil: ASTM D3487, Type II, and tested for compliance with ASTM D117.
- J. Sound level must comply with NEMA TR 1 requirements.
- K. Corrosion Protection:
  - 1. Transformer coating system must be factory applied, complying with requirements of IEEE C57.12.29, in manufacturer's standard color green.

## 2.3 THREE-PHASE TRANSFORMERS

- A. Manufacturers: Subject to compliance with requirements, provide products by one of the following:
  - 1. Eaton.
  - 2. GE Power; General Electric Company.
  - 3. Hitachi ABB Power Grids Ltd.; ABB & Hitachi Joint Venture.
- B. Description:
  - 1. Electrical Components, Devices, and Accessories: Listed and labeled in accordance with NFPA 70, by qualified electrical testing laboratory recognized by authorities having jurisdiction, and marked for intended location and application.
  - 2. Comply with IEEE C57.12.26.
- C. Compartment Construction:
  - 1. Double-Compartment Construction: Individual compartments for line- and load-side sections, formed by steel isolating barriers that extend full height and depth of compartments, with hinged, lift-off doors and three-point latching, with stop in open position and provision for padlocking.
- D. Primary Fusing: Designed and rated to provide thermal protection of transformer by sensing overcurrent and high liquid temperature.

1. 150 kV BIL current-limiting fuses, conforming to requirements of IEEE C37.47.
2. Interrupting Rating: 50 000 A(rms sym) at system voltage.
3. Fuse Assembly: Bayonet-type, liquid-immersed, expulsion fuses in series with liquid-immersed, partial-range, current-limiting fuses. Bayonet fuse must sense both high currents and high oil temperature to provide thermal protection to transformer. Connect current-limiting fuses ahead of radial-feed load-break switch.
4. Provide bayonet fuse assembly with oil retention valve and external drip shield inside housing to eliminate or minimize oil spills. Valve must close when fuse holder is removed and external drip shield is installed.
5. Provide conspicuously displayed warning adjacent to bayonet fuse(s), cautioning against removing or inserting fuses unless transformer has been de-energized and tank pressure has been released.

E. Line-Side Section: Dead-front design.

1. To connect primary cable, use separable insulated connectors; coordinated with and complying with requirements of Section 260513 "Medium-Voltage Cables." Bushings must be one-piece units, with ampere and BIL ratings same as connectors.
2. Bushing inserts:
  - a. Conform to requirements of IEEE 386.
  - b. Radial-feed, liquid-immersed type with voltage class and BIL matching that of separable connectors, with continuous current rating and load-break rating of 200 A, and make-and-latch rating of 12 kA(rms sym).
  - c. Loop-feed sectionalizing switches, using three two-position, liquid-immersed-type switches for closed transition loop-feed and sectionalizing operation. Voltage class and BIL must match that of separable connectors, with continuous current rating and load-break rating of 200 A, and make-and-latch rating of 12 kA(rms sym). Switch operation must be as follows:
    - 1) Position I: Line A connected to line B and both lines connected to transformer.
    - 2) Position II: Transformer connected to line A only.
    - 3) Position III: Transformer connected to line B only.
    - 4) Position IV: Transformer disconnected and line A not connected to line B.
    - 5) Position V: Transformer disconnected and line A connected to line B.
3. Ground pad.

F. Load-Side Section:

1. Bushings with spade terminals drilled for terminating number of conductors indicated on Drawings, and lugs that comply with requirements of Section 260519 "Low-Voltage Electrical Power Conductors and Cables."

G. Capacities and Characteristics:

1. Power Rating: As indicated on the drawings.
2. Voltage Ratings: 12.47 KV - 208Y/120 V.
3. Taps: Comply with IEEE C57.12.26 requirements.
4. Transformer BIL (kV): Comply with IEEE C57.12.26 requirements.
5. Minimum Tested Impedance (Percent) at 85 deg C: 4.03.
6. Comply with FM Global Class No. 3990.

7. Comply with UL listing requirements for combination classification and listing for transformer and less-flammable insulating liquid.

H. Transformer Accessories:

1. Drain and filter connection.
2. Filling and top filter press connections.
3. Pressure-vacuum gauge.
4. Dial-type analog thermometer with alarm contacts.
5. Magnetic liquid level indicator with high and low alarm contacts.
6. Automatically resetting pressure-relief device. Device flow must be as recommended by manufacturer. With alarm contacts and manual bleeder.
7. Stainless steel ground connection pads.
8. Machine-engraved nameplate, made of anodized aluminum or stainless steel.

## 2.4 WARNING LABELS AND SIGNS

- A. Comply with requirements for labels and signs specified in Section 260553 "Identification for Electrical Systems."
1. High-Voltage Warning Label: Provide self-adhesive warning signs on outside of line-side compartment door(s). Sign legend must be "DANGER HIGH VOLTAGE" printed in two lines of nominal 2 inch (50 mm) high letters. Word "DANGER" must be in white letters on red background and words "HIGH VOLTAGE" must be in black letters on white background.
  2. Arc Flash Warning Label: Provide self-adhesive warning signs on outside of line-side compartment door(s), warning of potential electrical arc flash hazards and appropriate personal protective equipment required.

## 2.5 SOURCE QUALITY CONTROL

- A. Testing Administrant: Engage qualified electrical testing agency to evaluate transformer.
- B. Testing: Test and inspect transformer in accordance with IEEE C57.12.90.
- C. Factory Tests and Inspections: Perform the following tests and inspections, by, or under supervision of, qualified electrical testing laboratory recognized by authorities having jurisdiction, before delivering to site. Affix label with name and date of manufacturer's certification of system compliance on control units.
1. Resistance.
  2. Turns ratio, polarity, and phase relation.
  3. Transformer no-load losses and excitation current at 100 percent of ratings.
  4. Transformer impedance voltage and load loss.
  5. Operation of devices.
  6. Lightning impulse.
  7. Low frequency.
  8. Leak.
  9. Perform Optional Tests:
    - a. Transformer no-load losses and excitation current at 110 percent of ratings.
    - b. Insulation power factor.

- c. Applied potential, except that this test is not required for single-phase transformers or for three-phase Y-Y-connected transformers.
- d. Induced potential.
- e. Resistance measurements of windings on rated voltage connection and at tap extreme connections.
- f. Ratios on rated voltage connection and at tap extreme connections.
- g. Polarity and phase relation on rated voltage connection.
- h. No-load loss at rated voltage on rated voltage connection.
- i. Exciting current at rated voltage on rated voltage connection.
- j. Impedance.

## **PART 3 - EXECUTION**

### **3.1 EXAMINATION**

#### **A. Examine pad-mounted, liquid-filled, medium-voltage transformers upon delivery.**

1. Upon delivery of transformers and prior to unloading, inspect equipment for damage that may have occurred during shipment or storage.
2. Verify that tie rods and chains are undamaged and tight, and that blocking and bracing is tight. Verify that there is no evidence of load shifting in transit, and that readings from transportation shock recorders, if equipped, are within manufacturer's recommendations.
3. Verify that there is no indication of external damage and no dents or scratches in doors and sill, tank walls, radiators and fins, or termination provisions.
4. Verify that there is no evidence of insulating-liquid leakage on transformer surfaces, at weld seams, on line- or load-side bushing parts, and at transformer base.
5. Verify that there is positive pressure or vacuum on tank. Check pressure gauge; it is required to read other than zero.
6. Compare transformers and accessories received with bill of materials to verify that shipment is complete. Verify that transformers and accessories conform with manufacturer's quotation and shop drawings. If shipment is incomplete or does not comply with Project requirements, notify manufacturer in writing immediately.
7. Verify presence of polychlorinated biphenyl content labeling.
8. Unload transformers carefully, observing packing label warnings and handling instructions.
9. Open termination compartment doors and inspect components for damage or displaced parts, loose or broken connections, cracked or chipped insulators, bent mounting flanges, dirt or foreign material, and water or moisture.

#### **B. Handling:**

1. Handle transformers carefully, in accordance with manufacturer recommendations, to avoid damage to enclosure, termination compartments, base, frame, tank, and internal components. Do not subject transformers to impact, jolting, jarring, or rough handling.
2. Protect transformer termination compartments against entrance of dust, rain, and snow.
3. Transport transformers upright, to avoid internal stresses on core and coil mounting assembly and to prevent trapping air in windings. Do not tilt or tip transformers.
4. Verify that transformer weights are within rated capacity of handling equipment.
5. Use only manufacturer-recommended points for lifting, jacking, and pulling. Use lifting lugs when lifting transformers.
6. Use jacks only at corners of tank base plate.
7. Use nylon straps of same length to balance and distribute weight when handling transformers with crane.

8. Use spreaders or lifting beam to obtain vertical lift and to protect transformer from straps bearing against enclosure. Lifting cable pull angles may not be greater than 15 degrees from vertical.
9. Exercise care not to damage tank base structure when handling transformer using skids or rollers. Use skids to distribute stresses over tank base when using rollers under large transformers.

C. Storage:

1. Store transformers in accordance with manufacturer's recommendations.
2. Transformers may be stored outdoors. If possible, store transformers at final installation locations on concrete pads. If dry concrete surfaces are unavailable, use pallets of adequate strength to protect transformers from direct contact with ground. Ensure transformer is level.
3. Ensure that transformer storage location is clean and protected from severe conditions. Protect transformers from dirt, water, contamination, and physical damage. Do not store transformers in presence of corrosive or explosive gases. Protect transformers from weather when stored for more than three months.
4. Store transformers with compartment doors closed.
5. Regularly inspect transformers while in storage and maintain documentation of storage conditions, noting discrepancies or adverse conditions. Verify that effective pressure seal is maintained using pressure gauges. Visually check for insulating-liquid leaks and rust spots.

D. Examine areas and space conditions for compliance with requirements for pad-mounted, liquid-filled, medium-voltage transformers and other conditions affecting performance of the Work.

E. Examine roughing-in of conduits and grounding systems to verify the following:

1. Wiring entries comply with layout requirements.
2. Entries are within conduit-entry tolerances specified by manufacturer, and no feeders will cross section barriers to reach load or line lugs.

F. Examine concrete bases for suitable conditions for transformer installation.

G. Pre-Installation Checks:

1. Verify removal of shipping bracing after placement.
2. Remove sample of insulating liquid in accordance with ASTM D923. Insulating-liquid values must comply with NETA ATS, Table 100.4. Sample must be tested for the following:
  - a. Dielectric Breakdown Voltage: ASTM D877 or ASTM D1816.
  - b. Acid Neutralization Number: ASTM D974.

H. Verify that ground connections are in place and that requirements in Section 260526 "Grounding and Bonding for Electrical Systems" have been met. Maximum ground resistance must be 5  $\Omega$  at transformer location.

I. Proceed with installation only after unsatisfactory conditions have been corrected.

### **3.2 INSTALLATION**

- A. Install transformers on cast-in-place concrete equipment base(s). Comply with requirements for equipment bases and foundations specified in Section 260529 "Hangers and Supports for Electrical Systems."
- B. Transformer must be installed level and plumb and must tilt less than 1.5 degrees while energized.
- C. Comply with requirements for vibration isolation and seismic control devices specified in Section 260529 "Hangers and Supports for Electrical Systems".
- D. Maintain minimum clearances and workspace at equipment in accordance with manufacturer's published instructions and IEEE C2.

### **3.3 CONNECTIONS**

- A. Ground equipment in accordance with Section 260526 "Grounding and Bonding for Electrical Systems."
  - 1. For counterpoise, use tinned bare copper cable not smaller than 4/0 AWG, buried not less than 30 inch (765 mm) below grade interconnecting grounding electrodes. Bond surge arrester and neutrals directly to transformer enclosure and then to grounding electrode system with bare copper conductors, sized as shown. Keep lead lengths as short as practicable, with no kinks or sharp bends.
  - 2. Fence and equipment connections may not be smaller than 4 AWG. Ground fence at gate posts and corner posts and at intervals not exceeding 10 ft (3 m). Bond gate sections to fence posts using 1/8 by 1 inch (3 by 25 mm) flexible braided copper strap and clamps.
  - 3. Make joints in grounding conductors and loops by exothermic weld or compression connector.
  - 4. Terminate grounding and bonding conductors on common equipment grounding terminal on transformer enclosure.
  - 5. Complete transformer tank grounding and lightning arrester connections prior to making other electrical connections.
- B. Connect wiring in accordance with Section 260519 "Low-Voltage Electrical Power Conductors and Cables."
  - 1. Maintain air clearances between energized live parts and between live parts and ground for exposed connections in accordance with manufacturer recommendations.
  - 2. Bundle associated phase, neutral, and equipment grounding conductors together within transformer enclosure. Arrange conductors such that there is not excessive strain that could cause loose connections. Allow adequate slack for expansion and contraction of conductors.
- C. Terminate medium-voltage cables in incoming section of transformers in accordance with Section 260513 "Medium-Voltage Cables."

### **3.4 SIGNS AND LABELS**

- A. Comply with installation requirements for labels and signs specified in Section 260553 "Identification for Electrical Systems."



- B. Install warning signs as required to comply with 29 CFR 1910.269.

### 3.5 FIELD QUALITY CONTROL

#### A. Tests and Inspections:

##### 1. General Field-Testing Requirements:

- a. Comply with provisions of "Testing and Test Methods" Chapter in NFPA 70B.
- b. Perform visual and mechanical inspections and electrical tests. Certify compliance with test parameters.
- c. After installing transformer but before primary is energized, verify that grounding system at transformer is tested at specified value or less.
- d. After installing transformer and after electrical circuitry has been energized, test for compliance with requirements.
- e. Visual and Mechanical Inspection:
  - 1) Verify equipment nameplate data complies with Contract Documents.
  - 2) Inspect bolted electrical connections for high resistance using one of the following two methods:
    - a) Use low-resistance ohmmeter to compare bolted connection resistance values to values of similar connections. Investigate values that deviate from those of similar bolted connections by more than 50 percent of lowest value.
    - b) Verify tightness of accessible bolted electrical connections by calibrated torque-wrench method in accordance with manufacturer's published data or NETA ATS, Table 100.12. Bolt-torque levels must be in accordance with manufacturer's published data. In absence of manufacturer's published data, use NETA ATS, Table 100.12.

##### 2. Medium-Voltage Surge Arrester Field Tests:

- a. Visual and Mechanical Inspection:
  - 1) Inspect physical and mechanical condition.
  - 2) Verify arresters are clean.
  - 3) Verify that ground leads on devices are individually attached to ground bus or ground electrode.
- b. Electrical Test:
  - 1) Perform insulation-resistance test on arresters, phase terminal-to-ground. Apply voltage in accordance with manufacturer's published data. In absence of manufacturer's published data, comply with NETA ATS, Table 100.1. Replace units that fail to comply with recommended minimum insulation resistance listed in that table.
  - 2) Perform watts-loss test. Evaluate watts-loss values by comparison with similar units and test equipment manufacturer's published data.

3. Liquid-Filled Transformer Field Tests:

a. Visual and Mechanical Inspection:

- 1) Test dew point of tank gases if applicable.
- 2) Inspect anchorage, alignment, and grounding.
- 3) Verify bushings are clean.
- 4) Verify that alarm, control, and trip settings on temperature and level indicators are set and operate within manufacturer's recommended settings.
- 5) Verify that liquid level in tanks is within manufacturer's published tolerances.
- 6) Perform specific inspections and mechanical tests recommended by manufacturer.
- 7) Verify presence of transformer surge arresters and that their ratings are as specified.
- 8) Verify that as-left tap connections are as specified.

b. Electrical Tests:

- 1) Perform insulation-resistance tests winding-to-winding and windings-to-ground. Apply voltage in accordance with manufacturer's published data. In absence of manufacturer's published data, comply with NETA ATS, Table 100.5. Calculate polarization index; value of index may not be less than 1.0.
- 2) Perform power-factor or dissipation-factor tests on windings in accordance with test equipment manufacturer's published data. Maximum winding insulation power-factor/dissipation-factor values must be in accordance with manufacturer's published data. In absence of manufacturer's published data, comply with NETA ATS, Table 100.3.
- 3) Measure core insulation resistance at 500 V(dc) if core is insulated and core ground strap is removable. Core insulation-resistance values may not be less than 1 MΩ at 500 V(dc).
- 4) Perform power-factor or dissipation-factor tip-up test on windings greater than 2.5 kV.
- 5) Perform Optional Field Tests:
  - a) Perform turns-ratio tests at tap positions. Turns-ratio test results may not deviate by more than one-half percent from either adjacent coils or calculated ratio. If test fails, replace transformer.
  - b) Perform excitation-current test on each phase. Typical excitation-current test data pattern for three-legged core transformer is two similar current readings and one lower current reading. Investigate and correct if test shows different pattern.
  - c) Measure resistance of windings at tap connections, and record temperature-corrected winding-resistance values in Operations and Maintenance Manual.
  - d) Perform applied-voltage test on line- and load-side windings-to-ground. Comply with IEEE C57.12.91, Sections 10.2 and 10.9. This test is not required for single-phase transformers and for three-phase wye-wye-connected transformers.
- 6) Verify correct secondary voltage, phase-to-phase and phase-to-neutral, after energization and prior to loading.
- 7) Remove sample of insulating liquid in accordance with ASTM D923, and perform dissolved-gas analysis in accordance with IEEE C57.104 or ASTM D3612.

- B. Nonconforming Work:
  - 1. Equipment and devices will be considered defective if they do not pass tests and inspections.
  - 2. Remove and replace malfunctioning units and retest.
- C. Prepare test and inspection reports. Record as-left set points of adjustable devices.

### **3.6 FOLLOW-UP SERVICE**

- A. Voltage Monitoring and Adjusting: After Substantial Completion, if requested by Client Agency, but not more than six months after Final Acceptance, perform the following voltage monitoring:
  - 1. During period of normal load cycles as evaluated by Client Agency, perform seven days of three-phase voltage recording at outgoing section of transformers. Use voltmeters with calibration traceable to National Institute of Science and Technology standards and with chart speed of not less than 1 inch (25 mm) per hour. Voltage unbalance greater than 1 percent between phases, or deviation of phase voltage from nominal value by more than plus or minus 5 percent during test period, is unacceptable.
  - 2. Corrective Action: If test results are unacceptable, perform the following corrective action, as appropriate:
    - a. Adjust transformer taps.
    - b. Prepare written request for voltage adjustment by electric utility.
  - 3. Retests: Repeat monitoring, after corrective action is performed, until satisfactory results are obtained.
  - 4. Report:
    - a. Prepare written report covering monitoring performed and corrective action taken.
- B. Infrared Inspection: Perform survey during periods of maximum possible loading. Remove necessary covers prior to inspection.
  - 1. After Substantial Completion, but not more than 60 days after Final Acceptance, perform infrared inspection of transformer's electrical power connections.
  - 2. Instrument: Inspect distribution systems with imaging equipment capable of detecting minimum temperature difference of 1 deg C at 30 deg C.
  - 3. Record of Infrared Inspection: Prepare certified report that identifies testing technician and equipment used, and lists results as follows:
    - a. Description of equipment to be tested.
    - b. Discrepancies.
    - c. Temperature difference between area of concern and reference area.
    - d. Probable cause of temperature difference.
    - e. Areas inspected. Identify inaccessible and unobservable areas and equipment.
    - f. Identify load conditions at time of inspection.
    - g. Provide photographs and thermograms of deficient area.

4. Act on inspection results in accordance with recommendations of NETA ATS, Table 100.18. Correct possible and probable deficiencies as soon as Client Agency's operations permit. Retest until deficiencies are corrected.

**END OF SECTION**